

Did You Know?

Factsheet #4

Changes to BS 5839-1

Inspection and Servicing

Clause 45.1 now states that routine servicing of the system is not a review of the design, so that non-compliance with the design requirement of BS 5839-1 might not be identified during any routine servicing. The requirement for the standby battery to be disconnected and full load alarm to be simulated on the PSU has been replaced by Clause 45.3d, which now requires the battery voltage to be measured with the mains on to check the steady state charge voltage and check it is within the manufacturer's recommendations.

WMS Fire Systems
Unit 4 Site 3 Alma Park Road
Alma Park Industrial Estate
Grantham, Lincolnshire, NG31 9SE
Tel: 01476 564921